

Upgrade your firmware now to V1.5!

In order to upgrade your 1541 Ultimate or 1541 Ultimate Plus to version 1.5, download the following zip file:

[1541 Ultimate V1.5 Firmware Download](#)

Installation instructions:

- 1) Make sure that in your current configuration, the "application to boot" is set to "appl.bin" (the default).

- 2) Unzip the zip file into the ROOT of an SD-card, of which you have made sure that the 1541 Ultimate can read it.

- 3) Place the SD-card in the 1541U, and make sure the 1541U is correctly inserted in a C64/C128 expansion slot.

- 4) Turn on the C-64 and watch the screen output.

- 5) Turn off the C-64 when the update is finished.

In comparison to 1.5beta, the following small issues have been fixed:

- The menu waits until you release the keyboard before exiting.

- Show all entries in a D64 when loading directory through software IEC

Known issues:

- CD:/ of the software IEC mode is broken
- MOUNT: is partly broken (1541-bug-workaround was removed because we forgot why we did that! Temporary solution: Issue initialize command to 1541 after mounting a D64: @8, @I)